			POWER GRID COMPANY OF BANGLAD NATIONAL LOAD DESPATCH O DAILY REPORT					OF-LDC-0 Page -1
				***		Reporting Date:	13-Jan-15	1 age -
Till now the ma	ximum generation is	12-Jan-15	7418 MW Generation & Demand	21:00	Hrs on	18-Jul-14 Min Gen. & Proba	bla Can & Dar	
Day Peak Generati		4697.0	MW Hour:	9:00	Min. Gen. at	4:00	3143	MW
Evening Peak Gen		6041.0	MW Hour:	19:00	Max Generation		6151	MW
E.P. Demand (at go		6041.0	MW Hour:	19:00	Max Demand	:	6100	MW
Maximum Genera		6041.0	MW Hour:	19:00	Shortage		-51	MW
Total Gen. (MKW		110.1	System L/ Factor :	75.92%	Load Shed	:	0	MW
	,	EXPO	RT / IMPORT THROUGH EAST-WEST INTERCO	ONNECTOR				
Export from East g	grid to West grid :- Ma	aximum	-270	MW at	17:00	Energy	7.867	MKWHR.
Import from West	grid to East grid :- Ma		-	MW at	-	Energy	-	MKWHR.
			Lake at 6:00 A M on	13-Jan-15				
Actual :	87.64 Ft.	(MSL),	Rule cu	rve: 100.20	Ft.(MSL)			
Gas Consumed :	Total	762.02	MMCFD.	Oil Consumed (DDD).			
Gas Consumed :	1 otai	762.02	MMCFD.	Oii Consumed (PDB):	HSD :		Liter
						FO :		Liter
Cost of the Consur	ned Fuel (PDB+Pvt) :	Gas :	Tk61,381,779					
		Coal :	Tk0	Oil	: Tk282,110,799	Total : '	Γk343,492,578	
	Loa	1 Shedding & Othe	r Information					
Area	Yesterday				Today			
Aica	Testerday		Estimated Demand (S/S end)		Estimated Shedd	ling (\$/\$ and)	Rates of Shedo	lina
	MW		MW		Listinated Shede		On Estimated I	
Dhaka	-	0:00	2271			-	-	, cintaina)
Chittagong Area	_	0:00	580			-	_	
Khulna Area	_	0:00	633			-	_	
Rajshahi Area	-	0:00	616			-	-	
Comilla Area	-	0:00	425			-	-	
Mymensingh Area	-	0:00	353			-	-	
Sylhet Area	-	0:00	288			-	-	
Barisal Area	-	0:00	128			-	-	
Rangpur Area	-	0:00	361			-	-	
	-							
Total	0		5655			0		
	Information of the	Generating machin	es under shut down.					
	Planned Shut- Down			Forced Shut- Dov	wn			
	1) Haripur GT: Unit-3 (1	8/06/2009)		1) Ghorasal ST: U	nit-6 (18/07/2010)		99) Haripur 412	MW CCPP(02/01/2015)
				 Ashuganj ST: Unit-1(23/08/2014) Ashuganj ST: Unit-4 (05/01/2 				
				3) Khulna ST 110				Unit-4 (07/01/2015)
					PP-2 ST (07/11/2014)		12) Siddhirgonj S	
					5) Baghabari GT 100 MW (01/12/2014) 13) Barapukuria ST: Unit-1 (12/ 6) Sikalbaha Peaking GT (01/12/2014) 7) Chittagong ST: Unit-2(20/12/14)			s1: Unit-1 (12/01/2015)
					8) Barapukuria ST: Unit-2 (19/12/14)			
			s, Interruption / Forced Load shed etc.					
	Additional Informatio	ii or ivincinines, iiic						
	Additional Information	ii or muchines, inc		Forced load shad	led / Interrupted A	reas		
a) Kaptai-Hathaza	Description ri 132 kV Ckt-2 was ur	nder shut down from	m 08:52 to 17:02 due to A/M.	Forced load shad	led / Interrupted A	reas		
a) Kaptai-Hathaza b) Rajshahi 132/33	Description ri 132 kV Ckt-2 was ur 3 kV T-3 transformer w	nder shut down from	n 09:05 to 16:40 due to maintenance work.	Forced load shad	led / Interrupted A	reas		
a) Kaptai-Hathaza b) Rajshahi 132/33 c) Mirpur 132/33 k'	Description ri 132 kV Ckt-2 was ur 3 kV T-3 transformer was V T-3 transformer was	nder shut down from as under shut from shut down at 09:	n 09:05 to 16:40 due to maintenance work. 40 due to cable change.	Forced load shad	led / Interrupted A	reas		
a) Kaptai-Hathazai b) Rajshahi 132/33 c) Mirpur 132/33 k' d) Bogra-Barapuku	Description ri 132 kV Ckt-2 was ur 8 kV T-3 transformer w V T-3 transformer was uria 230 kV Ckt-2 was	nder shut down from as under shut from shut down at 09: shut down at 10:3:	n 09:05 to 16:40 due to maintenance work. 40 due to cable change. 2 due to Barapukuria P/S maintenance work.	Forced load shad	led / Interrupted A	reas		
a) Kaptai-Hathazai b) Rajshahi 132/33 k' c) Mirpur 132/33 k' d) Bogra-Barapuku e) Raozan unit-1 tr	Description ri 132 kV Ckt-2 was ur 8 kV T-3 transformer w V T-3 transformer was uria 230 kV Ckt-2 was ripped at 11:30 showin	nder shut down from as under shut from shut down at 09:- shut down at 10:3: g drum level high	n 09:05 to 16:40 due to maintenance work. 40 due to cable change. 2 due to Barapukuria P/S maintenance work. and was synchronized at 13:01.					
a) Kaptai-Hathazai b) Rajshahi 132/33 k d) Bogra-Barapuk e) Raozan unit-1 tr f) Rangpur 132/33	Description ri 132 kV Ckt-2 was ur kV T-3 transformer w V T-3 transformer was uria 230 kV Ckt-2 was ripped at 11:30 showir kV T3 transformer was	nder shut down from as under shut from shut down at 09:- shut down at 10:3: g drum level high	n 09:05 to 16:40 due to maintenance work. 40 due to cable change. 2 due to Barapukuria P/S maintenance work.	Power interruption	on occurred (about	reas t 10 MW) under Ran	gpur S/S areas	
a) Kaptai-Hathaza b) Rajshahi 132/33 c) Mirpur 132/33 k d) Bogra-Barapuki e) Raozan unit-1 tr f) Rangpur 132/33 switched on at 1	Description ri 132 kV Ckt-2 was ur 8 kV T-3 transformer w V T-3 transformer was uria 230 kV Ckt-2 was ripped at 11:30 showir kV T3 transformer wa 13:25.	ader shut down from as under shut from shut down at 09: shut down at 10:3: g drum level high s shut down at 11:	n 09:05 to 16:40 due to maintenance work. 40 due to cable change. 2d due to Bargulwiria P/S maintenance work. and was synchronized at 13:01. 30 due to CT clump change at 132 kV end and was	Power interruption	on occurred (about	t 10 MW) under Ran		
a) Kaptai-Hathazai b) Rajshahi 132/33 k d) Bogra-Barapuki e) Raozan unit-1 tr f) Rangpur 132/33 switched on at 1 g) Jamalpur 132/3	Description in 132 kV Ckt-2 was ur kV T-3 transformer w V T-3 transformer was uria 230 kV Ckt-2 was uria 230 kV Ckt-2 was uria 230 kV at 1:30 showir kV T3 transformer wa 13:25. 3 kV T-1 & 2 transform	ader shut down from as under shut from shut down at 09: shut down at 10:3: g drum level high s shut down at 11:	n 09:05 to 16:40 due to maintenance work. 40 due to cable change. 2 due to Barapukuria P/S maintenance work. and was synchronized at 13:01.	Power interruption from 11;30 to 13	on occurred (about :25. on occurred (about			
a) Kaptai-Hathaza b) Rajshahi 132/33 k' d) Bogra-Barapuku e) Raozan unit-1 tr f) Rangpur 132/33 switched on at 1 g) Jamalpur 132/33 switched on at	Description ri 132 kV Ckt-2 was ur 8 kV T-3 transformer w V T-3 transformer wa ria 230 kV Ckt-2 was ripped at 11:30 showir kV T3 transformer wa 3:25. 8 kV T-1 & 2 transform 18:04 respectively.	ader shut down from as under shut from shut down at 09: shut down at 10:3: g drum level high s shut down at 11: hers tripped at 17:5	109:05 to 16:40 due to maintenance work. 40 due to cable change. 2 due to Barapukuria P/S maintenance work. and was synchronized at 13:01. 30 due to CT clump change at 132 kV end and was	Power interruption	on occurred (about :25. on occurred (about	t 10 MW) under Ran		
a) Kaptai-Hathaza b) Rajshahi 132/33 k' d) Bogra-Barapuku e) Raozan unit-1 tr f) Rangpur 132/33 switched on at 1 g) Jamalpur 132/33 switched on at	Description in 132 kV Ckt-2 was ur kV T-3 transformer w V T-3 transformer was uria 230 kV Ckt-2 was uria 230 kV Ckt-2 was uria 230 kV at 1:30 showir kV T3 transformer wa 13:25. 3 kV T-1 & 2 transform	ader shut down from as under shut from shut down at 09: shut down at 10:3: g drum level high s shut down at 11: hers tripped at 17:5	109:05 to 16:40 due to maintenance work. 40 due to cable change. 2 due to Barapukuria P/S maintenance work. and was synchronized at 13:01. 30 due to CT clump change at 132 kV end and was	Power interruption from 11;30 to 13	on occurred (about :25. on occurred (about	t 10 MW) under Ran		
a) Kaptai-Hathaza b) Rajshahi 132/33 k' d) Bogra-Barapuku e) Raozan unit-1 tr f) Rangpur 132/33 switched on at 1 g) Jamalpur 132/33 switched on at	Description ri 132 kV Ckt-2 was ur 8 kV T-3 transformer w V T-3 transformer wa ria 230 kV Ckt-2 was ripped at 11:30 showir kV T3 transformer wa 3:25. 8 kV T-1 & 2 transform 18:04 respectively.	ader shut down from as under shut from shut down at 09: shut down at 10:3: g drum level high s shut down at 11: hers tripped at 17:5	109:05 to 16:40 due to maintenance work. 40 due to cable change. 2 due to Barapukuria P/S maintenance work. and was synchronized at 13:01. 30 due to CT clump change at 132 kV end and was	Power interruption from 11;30 to 13	on occurred (about :25. on occurred (about	t 10 MW) under Ran		
a) Kaptai-Hathaza b) Rajshahi 132/33 k' c) Mirpur 132/33 k' d) Bogra-Barapuku e) Raozan unit-1 tr f) Rangpur 132/33 switched on at 1 g) Jamalpur 132/3 switched on at	Description if 132 kV Ckt-2 was ur kV T-3 transformer wa vr-3 transformer was uria 230 kV Ckt-2 was ripped at 11:30 showir kV T3 transformer wa 3:25. 3 kV T-1 & 2 transform 18:04 respectively. iit-2 was synchronized	ader shut down from as under shut from shut down at 09: shut down at 10:3: g drum level high s shut down at 11: hers tripped at 17:5	109:05 to 16:40 due to maintenance work. 40 due to cable change. 2 due to Barapukuria P/S maintenance work. and was synchronized at 13:01. 30 due to CT clump change at 132 kV end and was	Power interruption from 11;30 to 13	on occurred (about :25. on occurred (about	t 10 MW) under Ran	alpur S/S areas	