

OF-LDC-08
Page -1

Reporting Date : 27-Oct-15
n 13-Aug-15

-Aug-15

Today's Actual Min Gen. & Probable Gen. & Demand									
--	--	--	--	--	--	--	--	--	--

Min. Gen. at	6:00	4763	MW
Max Generation	:	7705	MW
Max Demand	:	7700	MW
Shortage	:	5	MW
Load Shed	:	0	MW

KW.
KW.

•

umed (PDB) :

Liter
Liter

Total : Tk351,590,206

Today

Estimated Shedding (S/S end)	Rates of Shedding
------------------------------	-------------------

Estimated Shedding (S/S end), MW	Rules of Shedding (On Estimated Demand)
-------------------------------------	--

	MTW	(On Estimated Demand

	=	=
	-	-

—

100

—

100

100

100

100

	—	—
	—	—

1000

0

Information of the Generating machines under shut down.

Forced Shut- Down

- 1) Ghorasal ST: Unit-6 (18/09) Raozan ST: Unit-2 (18/10/2015)
- 2) Ashuganj ST: Unit-1 (12/10/10) Ashuganj : GT-2
- 3) Khulna 150 MW (16/10/2011) Summit Meghnaghat (25/10/2015)
- 4) Khulna ST 110 MW (04/11/2014)
- 5) Ghorasal ST: Unit-4 (05/01/2015)
- 6) Haripur GT-3
- 7) Sikalbaha ST
- 8) Haripur-412 MW (25/05/2015)

Additional Information of Machines, lines, Interruption / Forced Load shed etc.

Forced load shaded / Interrupted Areas

a) Faridpur 132/33 kV T1 transformer was under shut down from 08:02 to 15:23 due to A/M.
b) Bakulia-Khulshi 132 kV Ckt-1 was under shut down from 08:59 to 14:120 due to dead line checking.
c) Megnaghat 230 kV Bus-2 was under shut down from 09:26 to 17:59 due to A/M.
d) Barisal(N)-Bhola 230 kV Ckt-1 was shut down at 08:37 due to A/M.
e) Barisal(N) 230/132 kV T1 transformer was shut down 08:37 due to A/M.
f) KPCL-1 tripped at 09:01 due to voltage fluctuation and was synchronized at 09:09.
g) Comilla(N)-Bibiayana-2 tripped at 11:04 showing gen.trip and was switched on at 12:58.
h) Rampura 230 kV Bus-1 was under shut down from 08:27 to 16:56 due to A/M.
i) Chowmohani 132/33 kV T3 transformer was under shut down from 10:02 to 12:02 due to sky wire connection.
j) Rajshahi S/S-Rajshahi RPP 132 kV Ckt was under shut from 09:25 to 15:05 due to A/M.
k) Saidpur 132/33 kV T4 transformer was under shut down from 11:50 to 12:30 due to meter installation.
l) Saidpur-Purbasadipur 132 kV Ckt-2 was under shut down from 12:02 to 13:42 due to red hot maintenance at B-phase PT wave trap.
m) Bogra 132/33 kV T2 transformer was under shut down from 08:58 to 13:28 due to work of B-phase loop.
n) Jhenidah 132/33 kV T1 transformer & Bus- section-1 were under shut down from 09:50 to 11:30 due to connecting new Hatgopalpur PBS feeder.
o) Sylhet-150 MW tripped at 00:29(27/10/15) due to protection failure and was synchronized at 01:27(27/10/15).
p) Baghabari-71 MW was shut down at 05:50(27/10/15) due to air filter change and was synchronized at 11:05(27/10/15).

About 25 MW power interruption occurred under Jhenidah S/S area from 10:0

About 20 MW power interruption occurred under Jhenidah S/S area from 09:5

Superintendent Engineer
Load Dispatch Circle