POWER GRID COMPANY OF BANGLADESH LTD NATIONAL LOAD DESPATCH CENTER DAILY REPORT 20-Oct-23 Reporting Date 21:00 Hrs on 19-Apr-23 Today's Actual Min Gen. & Probable Gen. & Dema Min. Gen. at General Communication 27:00 Available Max Demand (Evening) . Reservet Generation end . Load Shot Till now the maximum generation is : The Summary of Yesterday's | PROUT | 12:00 | Hour | 12:00 | Hour | 19:00 | Hou 9025 14505 12500 2005 Evening Peak Generation E.P. Demand (at gen end) Maximum Generation Total Gen. (MKWH) Export from East grid to West grid :- Maximum Import from West grid to East grid :- Maximum Water Level of Kaptai Lake at 6:00 A M on 21:00 Ft.(MSL) 105.41 107.80 Ft.(MSL) Gas Consumed : Total = 1016.10 MMCFD. Oil Consumed (PDB): HSD Cost of the Consumed Fuel (PDB+Pvt) Tk227.250.729 Coal Tk536,661,407 Oil : Tk483,694,353 Total: Tk1,247,606,490 Load Shedding & Other Information Area Today Estimated Shedding (S/S end) Rates of Shedding (On Estimated Demand) 0% Estimated Demand (S/S end) Dhaka Chittagong Area Khulna Area Rajshahi Area Cumilla Area Mymensingh Are Sylhet Area Barisal Area MW 4858 1336 1873 1628 1339 996 558 466 0:00 0:00 0:00 0:00 0:00 0:00 0:00 0% 0% 0% 0% 0% 0% 0% 0% Rangpur Area Total 0:00 910 1**3965** Information of the Generating Units under shut down Forced Shut-Down 1) Barapukuria ST: Unit- 1,2 2) Ghorasal-3,7 3) Shajibazar 330 MW 4) Baghabari-71,100 MW 5) Raozan unit-2 6) Siddhirganj 210 MW . Planned Shut- Down Additional Information of Machines, lines, Interruption / Forced Load shed etc. Remark Outage opalganj 132/33/V SIS T.I. T Scheduled SID Due to Annual maintenance. opalganj 132/33/V SIS T.I T Scheduled SID Due to Annual maintenance. haljadpur-Sirajganj 132/V Cik-1 Scheduled SID bue to Marual maintenance. haljadpur-Sirajganj 132/V Cik-1 Scheduled SID from Sirajganj 132/33/V end Due to Annual Maintenance work. haljadpur 132/33/V end Due to Annual Maintenance work. asiasheari 132/33/V SIS TZ-44/H TI Scheduled SID Due to Annual Maintenance. 08:21 16:30 16:00 Sealgiaghur 132/33.W ord Dus to Annual Maintenance work. Palashahri 132/33.W SS TR-404T HT Scheduled SID Due to Annual Maintenance. Palashahri 132/33.W SS TR-404T HT Scheduled SID Due to Annual Maintenance. Palashahri 132/33.W SS TR-404T LT Scheduled SID Due to Annual Maintenance. Jamangur-Mymensingh 132/V Sc Vct Scheduled SID from Chandraphona 132/33.W end Due to Annual Maintenance and from Madunaghat 132/33.W vend Due to For annual deadline checking and maintenance. Jamapur-Mymensingh 132/V Sct Scheduled SID from Jamapur 132/33.W end Due to Annual Maintenance work and from Mymensingh 132/V Sct Scheduled SID from Jamapur 132/33.W end Due to Annual Maintenance (breaker & bay). Nation 132/33.W SS TR-36/25T JL T Is restored. Fairdpur 132/33.W SS TR-36/25T JL T is restored. Fairdpur 132/33.W SS TR-36/25T JL T is restored. Fairdpur 132/33.W SS Transformer-2 LT is restored. Fenchuganj 2001/32/33.W SS Transformer-1 LT is restored. Fenchuganj 2001/32/33.W SS Transformer-2 LT is restored. Fenchuganj 2001/32/33.W SS Transformer-1 LT restored. Gopalganj IN-Madarapur 132.W Ckcl-1 Project Work SD trom Gopalganj 4001/32.W end. Gopalganj 2001/32/34.W SS ST Alexander-1 Project Work SD trom Gopalganj 4001/32.W end. Gopalganj 2001/32/34.W SS ST Alexander-1 LT restored SD Due to 132.W SS S. SD Bellong Cornective maintenance. Madarapur 1322/34.W SS ST 14.W Devent SD Due to 132.W SS S. SD Bellong Cornective maintenance 14:13 14:14 16:41 08:30 08:30 08:31 09:00 16:37 17:04 09:06 09:07 09:20 09:04 09:25 09:26 14:18 21:50 21:50 10:08 10:10 10:11 10:14 10:20 10:29 10:29 10:29 13:45 16:43 22:05 21:57 14:45 11:50 11:52 11:44 12:07 10:29 10:29 10:42 12:01 11:45 10:51 11:02 11:02 IBIPTC SIS 20D09C 20MVA HT Forced S/ID Due to 20l Ashtupanj TSK was sync. Iasnabad 230/132k/ S/S AUTO TR-1 HT is restored. Iasnabad 230/132k/ S/S AUTO TR-1 LT is restored. Iasnabad 310/132k/ S/S AUTO TR-1 LT is restored. Isibyana South 400 MW GT was sync. Isibyana South 400 MW GT was sync. Isibyana Switched on. Isibyana Score Switched on. Isibyana CCPP 225MW GT was sync. 12:17 12:57 13:07 13:23 13:37 14:16 14:41 Ashuganj CCPP 225MW GT was sync. Ammand 1300 MW (BIFPC1) units 2 was sync. Dumilla(N) 230/132/33KV SIS 132KV T-03 HT Tripped showing Lookout relay. Dumilla(N) 230/132/33KV SIS 132KV T-04 LT Tripped showing Over current relay. Danaphur 132/33KV SIS 422T LT Scheduled SID Due to Shutdown for station supply T-2 fuse maintenance. Danaphur 132/33KV SIS 422T HT Scheduled SID Due to Shutdown for station supply T-2 fuse maintenance. Maintenagra 132/33KV SIS Transformer 611- HT Tripped showing 1. DFR(F7T) 2. DFR REF(8TN)3. OCR(50/51M OCGR(50/51M) elays Due to LA Failure(P-ph). Maintenagra 12/31GXV SIS Auto Transformer-01(705T) HT Tripped showing 1. RET670 (Main -1) 2. RET670 (Main -2) elays Due to DPDC 132/33 XV LA fault. Maintenagra 2/30/13/XV SIS Auto Transformer-02 (7/5T) HT Tripped showing 1. RET670 (Main -1) 2. RET670 (Main -2) elays Due to DPDC 132/33 XV LA fault. 18:08 15:45 15:38 15:38 19:35 15:10 15:10 37 MW load interrup. 15:13 15:13 15:18 29 MW load interrup. 46 MW load interrup 15:18 16:17 156 MW load interrup Maniknagar 230/132k/ SIS Auto Transformer-01(7051) HT Tripped showing 1.RET670 (Main -1) 2.RET670 (Main -2) relays Due to DPOC 13223k VI & fauti. Maniknagar 230/132k/ SIS Auto Transformer-02 (7151) HT Tripped showing 1.RET670(Main-1) 2.RET670(Main-2) relays Due to DPOC 1323k/ VI & Fauti. Thakungaon 132/23k/ SIS 724(47) HT is restored. Thakungaon 132/23k/ SIS 724(47) HT is restored. Cumilla(s) 132/33k/ SIS 714(47) HT is cheduled SID Due to Tr-01 Transformer Shift from India Bus to Bangladesh Bus. Biblyians South 400 MW ST was sync. Meghnaghat Summit COPP 305kW/ GT1 was shutdown due to gas shortage. Sythet COPP 250 MW was shutdown due to air filter replacement. Meghnaghat COPP 450 MW GT1 was shutdown due to gas shortage. Rampal Unit 2 was shutdown for testing. Cumilla(h)-Cumilla(S) 132 KV Ckt-3 Scheduled SiD from Cumilla(s) 132/33kV end Due to 132 KV Bus SiD from Cumilla(N) End. Cumilla(h)-Cumilla(S) 132 kV Ckt-1 Scheduled SiD from Cumilla(s) 132/33kV end Due to 132 KV Bus SiD from Cumilla(N) End. Cumilla(h)-Cumilla(S) 132 kV Ckt-1 Scheduled SiD from Cumilla(S) 132/33kV end Due to 132 KV Bus SiD from Cumilla(N) End. Cumilla(h)-Cumilla(S) 132 kV Ckt-1 Scheduled SiD from Cumilla(S) 132/33kV end Due to 132 KV Bus SiD from Cumilla(N) End. 15:18 16:40 16:30 16:31 17:02 30 MW load interrup 16:44 16:44 17:02 22:22 23:25 00:45 05:54 05:54 05:54

Dumilla(N)-Cumilla(N) 132 kV Ckt-1 Scheduled SID from Cumilla(N) 122/33kV end Due to 132 kV Bus SID from Cumilla (N) End Rampura 230/132kV SIS Auto Transformer - 0.1 T Scheduled SID Due to Main tank oil centrifuge.

Rampura 230/132kV SIS Auto Transformer - 01 HT Scheduled SID Due to Main tank oil centrifuge.

Galakori-Tangal 132kV Ckt-2 Project Work SID from Kalakori 40/0230/132kV end Due to work at mirzapur.

Galakori-Tangal 132kV Ckt-1 Tripped from Kallakori 40/0230/132kV end be tow kvok at mirzapur.

Galakori-Tangal 132kV Ckt-1 Tripped from Kallakori 40/0/230/132kV end showing Dir O/C 40/0/230/132kV e

06:09 06:09 06:19 06:30

6:40